
# EVIDENCE

- Surveys that happened after the OGS
- Fence corners and fence lines
- Witness testimony
- Deeds
- Subdivision Plats
- Cemetery Plats
- Road Records

# Surveys Subsequent to the Original Government Survey






# Surveys Subsequent to the Original Government Survey



Surveyors (often a County Surveyor) utilized and perpetuated PLSS corners





# Sometimes they set "stuff"

Plow shares Gun barrels Railroad spikes

Pipes Grader blades Drag teeth Stones

Buggy axels Window Weights Iron bars Bricks










# Town of Bangor 1867


Henry Bliss - County Surveyor




T19N R04W T19N R05W Town of Little Falls	Town of New Lyme T19N R03W	Town of Grant T19N R02W	illagg of Harron's T19N R01W Town of Lincoln	T19N R01E Town of Scott
T18N R04W	T18N R03W Town of La Fayette	T18N R02W Town of Greenfield	Town of La Grange T18N R01W	Town of Byron  Village of Wyeville  TVBA B01E
Town of Sparta T17N ROWN	T17N R03W Town of Angelo	T17N R02W Town of Adrian	T17N RO1W Town of Tomah	Village of Oakdale  Town of Oakdale  T17N R01E
T16N R04W Town of Leon	T16N R03W Town of Wells	Town of Ridgeville T16N R02W Village of Vorwalk	T16N R01W Town of Wilton  Village of Wilton	T16N R01E Town of Clifton
T15N R04W Town of Portland	T15N R03W Town of Jefferson	T15N R02W Town of Sheldon	T15N R01W  Town of Wellington	Village Kendall  Town of Glendale  T15N R01E

# Monroe County Surveyor Fred Holden 1900-1911






# Monroe County Surveyor Fred Holden 1900-1911



-	DESCRIPTION TOWNShip	ON of Section, 19 North, R	Quai Cang	rter Section	and Quar East of	ter quarte	er Sectio cipal Me	n Corners ridian.	of Section	
Application .	N. B.—The variation of need	lle adopted in establis	shing o	corners is		·•				
BOTH	Government Corners.	Bearing Trees.	In. dia.	Courses they bear.	Links Distant	Bearing Tre	es. In dia.	Courses they bear.	Links Distant,	
Original	N.W. Sec. cor. indentified N. E. Sec. cor. indentified S. E. Sec. cor. indentified	Evo Red O	8	N21 20 N 3-20	33/2	200 200	57	850/28	331/2 Stor	u×Ma
Original	4 S.W. Sec. cor. indentified N. 1 Sec. cor. indentified B. E. 1 Sec. cor. indentified S. 1 Sec. cor. indentified S. 1 Sec. cor. indentified	200	6	N89 W	mark	ollus	Ther			
	W. 1 Sec. cor. indentified	Redo	12	825€	2.6-	200	13	N69/2W	35	
10 10 10 10 11 11 12 14	NO. SUBDIVISION CORNERS.  1 Center \( \frac{1}{2} \) Sec. cor.  2 North \( \frac{1}{2} \) S N. W. qr.  3 East \( \frac{1}{2} \) S N. W. qr.  4 South \( \frac{1}{2} \) S N. W. qr.  5 West \( \frac{1}{2} \) S N. W. qr.  6 Center \( \frac{1}{2} \) S N. E. qr.  7 North \( \frac{1}{2} \) S N. E. qr.  8 East \( \frac{1}{2} \) S N. E. qr.  9 South \( \frac{1}{2} \) S N. E. qr.  10 Center \( \frac{1}{2} \) S S. E. qr.  2 South \( \frac{1}{2} \) S S. E. qr.  3 West \( \frac{1}{2} \) S S. E. qr.  5 Center \( \frac{1}{2} \) S S. E. qr.  6 West \( \frac{1}{2} \) S S. W. qr.	Bo Ivo Stake at Stake at "	1	STY/LE NB3 E Course when East	28 64	wo fo		r 68 W PSTW Corre	24 79	ach
17	7 Center 1-18 S. W. qr.	wo the	12	843/20	125	Stone a	et com	n X hn	ach.	
20 200 12 21 foron	878 - 6 4 Stone x	Store at Cor Story NAME	SO	F SWOR	N ASSIS	TANTS.	mark			
CV.	CHAINMEN.			FLAGI	MEN.	1		AXMEN.	of the second se	
Hiran	n Zaite		1 so	Will Mile W B	Srah	ans l	Pen Pan	y Och	gan	7

## Monroe County Surveyor Fred Holden 1900-1911



DESCRIPTION of Section, Quarter Section and Quarter quarter Section Corners of Section

13 Township 19 North, Range 2 East of 4 Principal Meridian.

N. B.—The variation of needle adopted in establishing corners is......

	Government Corners.	Bearing Trees.	In. dia.	Courses they bear.	Links Distant	Bearing Trees.	In dia,	Courses they bear.	Links Distant,
Riestati Originis	No.	Redo	7	N2120 N3-20	33/2	200	57	850/28	33/2 Stow x mark
Original	4 S. W. Sec. cor. indentified  5 N. 1 Sec. cor. indentified	Stone at	Cor	189 W	mark 37	otherh	er	goure	
Ongrido	7 S. 1 Sec. cor. indentified 8 W. 1 Sec. cor. indentified	Redo	12	825€	25-	200	13	N68/220	35-

North between Sections 13814 Canation 7 45 East 22.63 White Oak 17 Finches in diameter Hed Oak 12 825 & 25 links White Oak 13 A 692 635 . 80.00 Let fort comer to Sections 11.12.13814

## Original corner John Davidson 1853

Set quarter section post Red Oak 12 S25E 25 links White Oak 13 N69½W 35 links

DESCRIPTION of Section, Quarter Section and Quarter quarter Section Corners of Section

13 Township 19 North, Range 2 East of 4 Principal Meridian.

N. B.—The variation of needle adopted in establishing corners is.....

Government Corners	Bearing Trees.	In.	Courses	Links	Bearing Trees.	In	Courses	Links
Resitablished		dia.	they bear.	Distant	During Trees,	dia.	they bear.	Distant.
Ougrical 1 N.W. Sec. cor. indentified	200	7	N2120	33/2	200	5	850/28	331/2 Stow x mark
2 N. E. Sec. cor. indentified 3 S. E. Sec. cor. indentified		8	15-20	27	wo	7	86120	67
1 0 777 0	l - 1	Con	men ×		100		100 magain 400 magain 100 magain	
5 N. 4 Sec. cor. indentified E. 4 Sec. cor. indentified	200	6	N89 20	37	othersh	ei	goure	
Original W. 1 Sec. cor. indentified	10.34	12	825€	25-	200		~69/2 W	
Joen Con Internet	April Manager	17	722				/2.w	

Fred Holden County Surveyor 1902

# CHAINMEN. CHAINMEN. FLAGMEN. AXMEN. AXMEN. AXMEN. ALERIC Organ John Zahate John Mahan Berry Surron J. M. Birkhahy

Hiram Hall John Zahrte Harry Hiles John Graham G H Birkholz

Leslie Organ Perry Sisson

No.	59

History of corner establishment since Original Government Survey

21902142000

THE SURVE

Bryan H. Meyer \_\_\_. do hereby certify that on the July 19 83 . I found (evidence) are evidence of the West 14 corner of Section 13 R 2 W Fourth Principal Meridian, and I reestablished said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 18th day of July 1983.

Deputy County Surveyor

Date: July 7, 1983 - 11:00 A.M.

Weather: Clear, Humid, 80°+.

Witnesses to corner location:

Bryan H. Meyer

Dallas Wilhite


Fred A. Holden was here in April of 1902.


Description of corner evidence found:

I found a stone with a cross, 3'+ East of a 4-way fence corner. After further investigation, we found 2 flat stones lying on the South side of the corner stone. On these stones we found writing etched in in them. One said"H. Hiles" "A.17". The other said "J. Zahrte" "E% S14" "Chainman". Courthouse records show that Harry Hiles and John Zahrte were both sworn assistants who helped Holden in his 1902 survey. It appears that the corner stone was set by Holden: therefore I accepted it as the corner.

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner: scale: 1" = 30!+ Maple

Approved: HARLEY A. SIME MONROE CO. SURVEYOR





T 19 N R 2 W

WISCONSIN

SURVEY CONT	ROL	ORDER
-------------	-----	-------

NOTE: The bearing trees shown are double blazed with the blazes facing Hor

rizontal	 the	corner.	Distances	are	to	nails	Ĭn	hacks	on	the	side	of	each	tree.	

Vertical		WISCONSIN COORDINATE SYSTEM							
	East (X)	North (Y)	Elevation (Z)	Zone					
Corner									
Control Sta. Name			0						

stone.

ny Village of Town	of Grant	
County of	Monro e	

OUNTY


Fred A. Holden was here in April of 1902.

Description of corner evidence found:

I found a stone with a cross, 3'+ East of a 4-way fence corner.

After further investigation, we found 2 flat stones lying on the South side of the corner stone. On these stones we found writing etched in in them. One said "H. Hiles" "A.17". The other said "J. Zahrte" "E% S14" "Chainman". Courthouse records show that Harry Hiles and John Zahrte were both sworn assistants who helped Holden in his 1902 survey. It appears that the corner stone was set by Holden; therefore I accepted it as the corner.





Many times however, we aren't so fortunate when it comes to finding direct evidence

# Sometimes we need to look further



# EVIDENCE AND MEASURMENTS

## Fence lines

## Fence corners






# Witness Testimony




# Deeds





# Subdivision Plats




# Cemeteries and Cemetery Plats



#### U. S. PUBLIC LAND SURVEY MONUMENT RECORD

SECTION 8 T 15 N, R 5 W, TOWN OF Washington

#### LA CROSSE COUNTY




Describe any record evidence, monument evidence, testimonial evidence or any other material evidence you considered and whether the monument was found or restored through acceptance of an obliterated evidence location.

To the North is the old Blinn family cemetery. In 1904 Fred Blinn deeded his farm to Hundt (as described in Volume 106 Deeds, Page 53) except for a 35 ft. square parcel in the Southwest corner of the SW-SE. This parcel was reserved for burial purposes. Using this 1904 description, I set the corner by lining in with the old fence to the North and measuring 35 feet South from the NW corner of the cemetery. The cemetery fences are very old. I would assume that the location of the corner was known when the fences were built. The South fence is probably off to the North because of the highway cut. Describe or show any material discrepancy between the location of the restored corner and that of the corner previously restored or reestablished.

#### RECORD OF DURABLE WITNESS MONUMENTS

NO	DESCRIPTION	BEARING	DISTANCE
ı	Concrete post at the NW corner of cemetery	North <u>+</u>	35'
2	Set new (.B, - <del>and cap</del> Existing-P.K. nail in Hass Road-centerline-	South <u>+</u>	13.08 13.14
3	To P.K. nail in unblazed 24" tamarack, 27"		<del>21.65-</del> <del>21.67-</del>
4	To center of concrete fence post		34.35'

13' 21.74'



PLAN VIEW DRAWING OF REFERENCE TIES


MAP SHOWING DISTANCE AND DIRECTION TO OTHER PUBLIC LAND SURVEY CORNERS USED FOR REESTABLISHING THE CORNER

Describe any record evidence, monument evidence, testimonial evidence or any other material evidence you considered and whether the monument was found or restored through acceptance of an obliterated evidence location.

To the North is the old Blinn family cemetery. In 1904 Fred Blinn deeded his farm to Hundt (as described in Volume 106 Deeds, Page 53) except for a 35 ft. square parcel in the Southwest corner of the SW-SE. This parcel was reserved for burial purposes. Using this 1904 description, I set the corner by lining in with the old fence to the North and measuring 35 feet South from the NW corner of the cemetery. The cemetery fences are very old. I would assume that the location of the corner was known when the fences were built. The South fence is probably off to the North because of the highway cut. Describe or show any material discrepancy between the location of the restored corner and that of the corner previously restored or reestablished.



# Town Road Records



Southeast corner of Section 4, T15N, R4W, Town of Portland, Monroe County, Wisconsin.





The Town Board of said Town did meet pursuant to such notice, at the time and place specified, and did thereupon adjourn the time of deciding upon such application until the day of 1916, at 10 o'clock in the force of said day, notice of said adjournment being publicly given, and forthwith filed in the office of the Town Clerk of such Town, and that upon such adjourned day, the said Town Board did again meet at the time and place specified, and after personally duly examining and viewing such highway, as required by law, did make the following order, to-wit:

## HIGHWAY ORDER.

Town of Tariland Ss.

Whereas, upon application of \_\_\_\_\_\_freeholders and \_\_\_\_\_upplicants for homesteads, unde the laws of the United States, occupying the same, residing in said Town of Paulana relaculing of a highway, which said proposed relacules is set forth and described in said application as follows: Beginning at an the Center of The highway running n & D along the look line of the ME & Deag Jawn 15 19 4 lo, ax a Fraint 4 rods Doubly The WE Corner of The WE'4 of The WE's, said See Fown and range, thense - Travel 89°, wear across the ME'y of the ME's of said Dection to a procest 39 was sait of the Hellow of before aid 28 4 of 28 4; thense north 63° leen 24 wood 4 links, thence north 17 2, west 76 rado 20 luxs to The north lines The new by the nE's suis Dea, Favor and range! thence north 1720 Wear 68 rods to the Center of highway in the Ded is of the AE's Dea4 town and range begarerack

## HIGHWAY ORDER.

5/1

COUNTY, ]
Town of Pareland SS.
Whereas, upon application offreeholders andapplicants for homesteads under
Whereas, upon application offreeholders andapplicants for homesteads, under the laws of the United States, occupying the same, residing in said Town offor the
of a highway, which said proposed celocales is set
Total and described in said application as follows: Beginning at C. A.
The highway running of a Dal. It
The highway running M & D along the east line of the ME's Dee 9 Januar 15 17 4 le. ax a Fraint
The WE
The WE'T, said See Journ and range, the
The race and range the



SURVEYOR FORM NO.

#### CERTIFIED LAND CORNER

### History of corner establishment since Original Government Survey

Portland town road records call for this corner to be 41 rods North of the intersection of 2 Town Roads. It does not appear that the Town Road described in said records was laid out by a surveyor, although said records do make calls for bearings and distances. Said records are dated June 3, 1916. Description of corner evidence found:

I searched in an area 676.50 feet (41 rods) North of the road intersection and at a proportionate distance between the North  $\frac{1}{4}$  corner of section 9 and the North  $\frac{1}{4}$  corner of Section 10. Found a stone with a cross on top, down 12". This stone fits the distance to said road intersection and said proportionate distance AMAZINGLY well! The is no record of this stone. I accepted the stone as the corner.

No. 27
2150404000

BRYAN H. MEYER
S-1712
TOMAH, WIS. OR HELLING

H. A. Sime and Associates P. O. Box 705, Tomah, WI Phone: (608)-372-5392


						Phone: (000)-3/2-5592
Description of corner and w	vitness monuments, re	ferences and accessories used to	perpetuate the original or re-	established location	of this corner:	
Crew: Meyer, Forsythe Date: December 12, 19				C-+ 2/4H-04	9 mayord image have	Section 9
Witnesses to corner location				o Set 3/4"x24 ∫ down 6"± in	" round iron bar	
John Kenworthy		FIE		{!	ROAD-	
Brian Forsythe		ro	et 3/4"x24" 36.40" appendiron bar 6.40" appendiron bar 6.40" appendiron bar 6.40" appendirent appendir			9
Bryan H. Meyer		Existing stone mor Set 3/4"x24" round North side of the of the chiselled of	nument down 12"±. I iron bar on the stone 0.33' North	33.52 K	et nail of AVE.	
		Set sign on the No powerpole facing t	orth side of the che corner.	#5F10W8	- SELMOS	• = LOCATION CORNER  T 15 N R 4 W
		The bearings shown netic hand compass	Hereon are may-	/	<b>%</b>	WISCONSIN
SURVEY CONTROL ORE	DER			/		
Horizontal			Set 3/4"x24" round iron bar			
Vertical		WISCONSIN CO	ORDINATE SYSTEM	• /		
	East (X)	North (Y)	Elevation (Z)	Zone	City, Village or Town of Port	land
Corner					County of Monwood	
Control Sta. Name					County of Monroe	

## History of corner establishment since Original Government Survey

Portland town road records call for this corner to be 41 rods North of the intersection of 2 Town Roads. It does not appear that the Town Road described in said records was laid out by a surveyor, although said records do make calls for bearings and distances. Said records are dated June 3, 1916. Description of corner evidence found:

I searched in an area 676.50 feet (41 rods) North of the road intersection and at a proportionate distance between the North ‡ corner of section 9 and the North ‡ corner of Section 10. Found a stone with a cross on top, down 12". This stone fits the distance to said road intersection and said proportionate distance AMAZINGLY well! The is no record of this stone. I accepted the stone as the corner.


# Measurements to evidence





This network of corners – our infrastructure is <u>vitally</u> important to land ownership, taxation, easements, etc.


NW 1/4		NW 1/4 NE 1/4 SW 1/4 NE 1/4		NE 1/4 NE 1/4 SE 1/4 NE 1/4	
S 1/2 NW 1/4 SE 1/4		SW 1/4 NE 1/4 SE 1/4	NE 1/4		
SW 1/4	E 1/2 SW 1/4 SE 1/4				

Typical Section Subdivisions









#### Once we get all the corners in the ground....



we're not done yet

#### Corner Maintenance





#### Corner Maintenance



1. Check the condition of the marker

2. Check the ties

3. Set a warning sign

# Please help us protect these important corner locations

# **PLEASE PROTECT NEARBY** SURVEY MARKER

IF LOCATION OF THIS MARK
IS ENDANGERED
PLEASE CONTACT
COUNTY SURVEYOR'S OFFICE

LaCrosse Sign Co.




If you know of a survey marker that is endangered, let a surveyor know!



These corners don't belong to the County Surveyor, they belong to every Wisconsin property owner.

# "Hey Bryan, do you have any "fun facts" about the PLSS in Wisconsin?"

#### PLSS HUMOR



#### Eugene Shepard

well-known Wisconsin land surveyor, timber cruiser and prankster

Captured a specimen in Section 37 in a Township near Rhinelander



## Did you know?





Yes, I am a geek!

And sometimes being a geek can get you places!


















## All because I'm a PLSS geek!

#### Wisconsin County Surveyors Association

#### 2019 Board of Directors



President: Bryan Meyer - La Crosse County

Vice-President: Ryan Duckart - Brown County

Secretary: Brenda Hemstead - State Cartographer's office

Treasurer: Steve Geiger - Polk County

Director: Laurence Johns III - Vernon County

Director: Wade Pettit - Clark County

Director: Rob Merry - Kenosha, Milwaukee, Walworth & Waukesha Counties


Meet four time each year in Neillsville

# CURRENT STATUS

• 34 FULL TIME

• 26 PART TIME

• 12 NONE





Bryan Meyer
212 6<sup>th</sup> Street North
La Crosse, Wisconsin 54601
608-785-9626
bmeyer@lacrossecounty.org



## Questions?

